

SUMMARY OF CHINO BASIN GROUNDWATER RECHARGE OPERATIONS

July 2015

Drainage System Basin	Recharge Volume (AF)*			Management Zone Subtotals	
	SW/LR	MW	RW		
San Antonio Channel Drainage System					
College Heights	-	-	N	MZ-1 141 AF**	
Upland	17	-	N		
Montclair 1, 2, 3 & 4	17	-	N		
Brooks	-	-	63		
West Cucamonga Channel Drainage System					
8th Street	44	-	-	MZ-2 806 AF**	
7th Street	-	-	-		
Ely 1, 2, & 3	285	-	102		
Minor Drainage					
Grove	37	N	N		
Cucamonga and Deer Creek Channel Drainage Systems					
Turner 1 & 2	-	-	-		
Turner 3 & 4	87	-	85		
Day Creek Channel Drainage System					
Lower Day	17	-	X		
Etiwanda Channel Drainage System					
Etiwanda Debris	2	-	X		
Victoria	4	-	139		
San Sevaine Channel Drainage System					
San Sevaine 1, 2, 3, & 4	4	-	-		
San Sevaine 5	5	-	-		
West Fontana Channel System					
Hickory	-	-	39		
Banana	-	-	54		
Declez Channel Drainage System					
RP3 Cells 1,3, & 4	105	-	268	MZ-3 505 AF**	
RP3 Cell 2	29	-	-		
Declez	49	-	-		
Non-Replenishment Recharge**					
Brooks (MVWD) MZ-1	-				
Montclair (MVWD) MZ-1	-				
Turner (CVWD) MZ-2	-				
Month Total = 1,452 AF	702	0.0	750	July 2015	
Fiscal Year to Date Total				Fiscal Year to Date	
Since July 1, 2015 = 1,452 AF	702	0.0	750		
Calendar Year to Date Total				Calendar Year to Date	
Since Jan. 1, 2015 = 10,272 AF	3,463	0.0	6,809		

SW : Storm Water, LR : Local Runoff (and GE, MVWD), MW : MWD Imported Water, RW : Recycled Water

- : No stormwater/local runoff, or basin not in use due to maintenance or testing.

X : Turnouts not available - to be installed during future projects.

N : No turnout planned for installation.

* : Data are preliminary based on the data available at the time of this report preparation.

** : Management Zone Subtotals have deducted from them any Non-Replenishment Recharge, which is recharge originating from pumped groundwater and is not new water.