

SUMMARY OF CHINO BASIN GROUNDWATER RECHARGE OPERATIONS

July 2014

Drainage System Basin	Recharge Volume (AF)*			Management Zone Subtotals	
	SW/LR	MW	RW		
San Antonio Channel Drainage System					
College Heights	-	-	N	MZ-1 105 AF**	
Upland	-	-	N		
Montclair 1, 2, 3 & 4	17	-	N		
Brooks	-	-	72		
West Cucamonga Channel Drainage System					
8th Street	25	-	8	MZ-2 341 AF**	
7th Street	-	-	-		
Ely 1, 2, & 3	16	-	101		
Minor Drainage					
Grove	2	N	N		
Cucamonga and Deer Creek Channel Drainage Systems					
Turner 1 & 2	-	-	-		
Turner 3 & 4	11	-	-		
Day Creek Channel Drainage System					
Lower Day	-	-	X		
Etiwanda Channel Drainage System					
Etiwanda Debris	-	-	X		
Victoria	2	-	91		
San Sevaine Channel Drainage System					
San Sevaine 1, 2, 3, & 4	-	-	-		
San Sevaine 5	-	-	-		
West Fontana Channel System					
Hickory	-	-	118		
Banana	-	-	-		
Declez Channel Drainage System					
RP3 Cells 1,3, & 4	6	-	184		
RP3 Cell 2	3	-	-		
Declez	2	-	-		
Non-Replenishment Recharge**					
Brooks (MVWD) MZ-1	-				
Montclair (MVWD) MZ-1	(17)				
Turner (SAWCO) MZ-2	-				
Month Total = 641 AF	67	0.0	574	July 2014	
Fiscal Year to Date Total				Fiscal Year	
Since July 1, 2014 = 641 AF	67	0.0	574	to Date	
Calendar Year to Date Total				Calendar Year	
Since Jan. 1, 2014 = 9,746 AF	2,155	0.0	7,591	to Date	

SW : Storm Water, LR : Local Runoff (and GE, MVWD), MW : MWD Imported Water, RW : Recycled Water

- : No stormwater/local runoff, or basin not in use due to maintenance or testing.

X : Turnouts not available - to be installed during future projects.

N : No turnout planned for installation.

* : Data are preliminary based on the data available at the time of this report preparation.

** : Management Zone Subtotals have deducted from them any Non-Replenishment Recharge, which is recharge originating from pumped groundwater and is not new water.